


Photo Album for Muscatine Fire Department, IA

Job 31788

March 30, 2018

This week the cab made progress in initial assembly while the frame started in the chassis assembly area. In addition the pump house completed paint and then had trim added while the body completed paint. Next the cab should be merged with the chassis followed by the pump house while the body goes through initial assembly.



DSC04379



DSC04380



DSC04381



DSC04382




DSC04383




DSC04296



DSC04297



DSC04298



DSC04299



DSC04300



DSC04301



DSC04302



DSC04303



DSC04304



DSC04305



DSC04306



DSC04307



DSC04308



DSC04309



DSC04310



DSC04311



DSC04312



DSC04313



DSC04314




DSC04315




DSC04316



DSC04317



DSC04318



DSC04319



DSC04320



DSC04321



DSC04322



DSC04323



DSC04324



DSC00084



DSC00085



DSC00086



DSC00087



DSC00088



DSC00586



DSC00587



DSC00588



DSC00589



DSC00590



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2018 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956

