Photo Album for Jesup Fire Department, IA Job 35204 January 22, 2021

In this report your cab started in paint while the pump house began assembly and body fabrication started. In your next report the cab may make progress in paint while pump house assembly and body fabrication continue.



DSC06810



DSC06812



DSC06811



DSC06813





DSC06814



DSC00188



DSC00187



DSC00189





DSC00190



DSC00192



DSC00191



DSC00193





DSC00153



DSC00155



DSC00154




DSC00156









DSC00158





http://reliantfire.com/



An Oshkosh Corporation Company

