




Photo Album for Onalaska Fire Department, WI Job 35342 January 15, 2021

In this report your cab is staged for assembly while the frame was built, the PUC module is staged, the pedestal arrived, and the body began in paint. In your next report your cab may begin assembly while the frame build continues, the PUC module is staged, and the body continues in paint.



DSC02053



DSC02054




DSC02055



DSC02056



DSC02057



DSC07265



DSC07266



DSC07267



DSC07268



DSC07269



DSC02154



DSC02155



DSC02156



DSC02157



DSC02158




DSC02159



DSC02160



DSC02161




DSC00492



DSC00493



DSC00494



DSC07310



DSC07311



DSC07312



DSC07313



DSC07314



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956