



Photo Album for Onalaska Fire Department, WI Job 35342 January 22, 2021

In this report your cab started assembly while the frame had power train installed, the PUC module is staged, the pedestal was assembled, and the body made progress in paint. In your next report your cab & PUC module may be merged with the chassis while the body may begin initial assembly.



DSC07445



DSC07446




DSC07447



DSC07448



DSC07449



DSC07375



DSC07376



DSC07377



DSC07378



DSC07379



DSC07380



DSC07381



DSC07382



DSC06990



DSC06991




DSC06992



DSC06993



DSC06994



DSC00477



DSC00478



DSC00479



DSC00480



DSC00481



DSC06879



DSC06880



DSC06881



DSC06882



DSC06883



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956