

Photo Album for Tess Corners Volunteer Fire Dept., WI Job 35030 January 08, 2021

In this report your cab completed paint and is now in assembly while the frame build started, the pump was merged with the structure, the torque box is staged, and the body modules have started in paint. In your next report your cab may be merged with the chassis followed by the pump house, the torque box may begin assembly and the body modules may make progress in paint.



DSC07826




DSC07827



DSC07828



DSC07829



DSC07830



DSC04144



DSC04145



DSC04146



DSC04147



DSC04148




DSC00153



DSC00154



DSC00155



DSC00156




DSC00157



DSC00158



DSC00159



DSC04311



DSC04312




DSC04313



DSC04314



DSC04315




DSC04192



DSC04193



DSC04194



DSC04226



DSC04227



DSC04228



DSC04229



DSC04230



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956