



Photo Album for Tess Corners Volunteer Fire Dept., WI Job 35030 January 15, 2021

In this report your cab continued in assembly, the frame had powertrain installed, the pump house completed assembly, the torque box is staged, and the body modules completed paint. In your next report the cab may make progress in assembly followed by installation on the chassis followed by the pump house while the torque box may begin assembly and the body modules may be staged.



DSC07490



DSC07491



DSC07492



DSC07493



DSC07494



DSC08115



DSC08116



DSC08117



DSC08118



DSC08119



DSC08120



DSC08121



DSC08122



DSC02127



DSC02128



DSC02129



DSC02130



DSC02131



DSC02132



DSC00567



DSC00568



DSC00569



DSC02032



DSC02033



DSC02034



DSC02035



DSC02036



DSC02672



DSC02673



DSC02674



DSC02675



DSC02676



DSC02677



DSC02678




DSC02679



DSC02680



DSC02681



DSC02682



DSC02683



DSC02684



DSC02685



DSC02686



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956