



Photo Album for Eldridge Fire Department, IA Job F7334 February 19, 2021

In this report the cab is in paint while the frame rails have arrived, the pump house has begun refurbishment, the body is in paint, and the ladder sections have arrived. The torque box was unavailable for photos. In the next report the cab and body may make progress in paint while the chassis may begin assembly, and the pump house continues refurbishment.

Your next scheduled report from Weyauwega is the week ending March 06, 2021.



DSC09034



DSC09068



DSC09069



DSC09070



DSC09058



DSC09059



DSC09060




DSC09061



DSC09062



DSC09063



DSC09029



DSC09030



DSC09031



DSC09032



DSC09033



DSC09066



DSC09067



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

