## Photo Album for Jesup Fire Department, IA Job 35204 January 29, 2021

In this report your cab made progress in paint while the frame build started, the pump house is painted, and the body fabrication is complete with release to paint. In your next report the cab may complete the paint process while the frame build continues, the pump house is staged, and the body makes progress in paint.



DSC06826



DSC06828

Find us on Facebook



DSC06827



DSC06829




DSC06830



DSC06762



DSC06761



DSC06763



DSC06764



DSC09132



DSC06765



DSC09133





DSC09134



DSC09136



DSC09135



DSC06938





DSC06939



DSC06941

Find us on Facebook



DSC06940



DSC06942



http://reliantfire.com/



**An Oshkosh Corporation Company** 



