



# Photo Album for Jesup Fire Department, IA Job 35204 February 05, 2021

In this report your cab has started assembly while the frame build started, the pump house is staged, and the body completed paint . In your next report the cab may be merged with the chassis followed by the pump house while the body may begin initial assembly.



DSC02274



DSC02275



DSC02276




DSC02277



DSC02278



DSC02279



DSC02197



DSC02198



DSC02199



DSC02200



DSC02201



DSC02202



DSC06528



DSC06529




DSC06530



DSC06531



DSC06532



DSC06597



DSC06598



DSC06599



DSC06600



DSC06601



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956