



# Photo Album for Tess Corners Volunteer Fire Dept., WI Job 35030 January 29, 2021

In this report the torque box was merged with the chassis followed by installation of the body while the front body module completed initial assembly. In your next report the front body module may be installed on the chassis followed by the start of final assembly.



DSC01967



DSC01968



DSC01969



DSC01970



DSC01971



DSC01972



DSC01973



DSC01974



DSC01975



DSC01976



DSC01977



DSC01978



DSC01979



DSC01980



DSC01981



DSC01982




DSC01983



DSC01984



DSC01985



DSC01986



DSC01987



DSC01988



DSC01989



DSC01990



DSC01991



DSC01992




DSC01993



DSC01994





DSC01995



DSC01996



DSC01997



DSC01998



DSC01999



DSC02000




DSC02001



DSC02002



DSC02003



DSC02004



DSC02005



DSC02006



DSC02007



DSC02008



DSC02009



DSC02010



DSC02011



DSC02012



DSC02013



DSC02014



DSC02015



DSC02016



DSC02017



DSC02018




DSC02019



DSC02020



DSC02021



DSC02022



DSC02023



DSC02024



DSC02025



DSC02026





DSC02027



DSC02028



DSC02029



DSC02030




DSC02031



DSC02032



DSC01962



DSC01963



DSC01964



DSC01965



DSC01966



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956