Photo Album for Eldridge Fire Department, IA Job F7334 March 05, 2021

In this report the cab was not available in paint while the chassis is being built, the pump house is released to paint, the body is in paint, the torque box has returned, and the ladder sections are being assembled. In the next report the cab, pump house, and body may make progress in paint while the aerial device continues assembly, and the torque box is staged.

Your next scheduled report from Weyauwega is the week ending March 20, 2021.



DSC09114



DSC09116



DSC09115




DSC09117





DSC09118



DSC09101




DSC09100



DSC09102





DSC09094



DSC09096



DSC09095



DSC09119





DSC09120



DSC09122



DSC09121



DSC09123





DSC09083



DSC09085



DSC09084



DSC09086





DSC09087





http://reliantfire.com/



An Oshkosh Corporation Company



