




Photo Album for Eldridge Fire Department, IA Job F7334 March 19, 2021

In this report the cab has completed paint, the chassis is in assembly, the pump house has been merged with the chassis, the body has completed paint, the torque box is staged, and the aerial continues assembly. In the next report the cab, torque box, and body may be staged, while assembly continues with the chassis and the aerial device.

Your next scheduled report from Weyauwega is the week ending April 03, 2021.



DSC09052



DSC09053




DSC09054



DSC09000



DSC09001




DSC09002



DSC09003



DSC09004




DSC09005




DSC09006



DSC09007



DSC09008



DSC09009



DSC09010



DSC09011



DSC09047



DSC09048



DSC09049



DSC09050



DSC09051



DSC09041



DSC09042



DSC09043



DSC09012



DSC09013



DSC09014



DSC09015



DSC09016



DSC09017



DSC09018



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2020 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956