Photo Album for Hudson Fire Department, IA Job 35651 April 23, 2021

In this report your cab started in paint while the pump house started assembly, and body fabrication completed. In your next report your cab continue in paint while the pump house assembly may continue, and the body may start the paint process.



DSC04907



DSC04909



DSC04908



DSC04910





DSC04911



DSC00149



DSC00148




DSC00150





DSC00151



DSC04937



DSC00152



DSC04938





DSC04939



DSC04941



DSC04940





http://reliantfire.com/



An Oshkosh Corporation Company

