

Photo Album for Waterloo Fire Rescue, IA Job 35603 April 02, 2021

In this report your cab began the paint process while the pump house structure was fabricated. In your next report your cab may make progress in paint while the pump house may begin assembly.



DSC00093



DSC00094



DSC00095



DSC00097



DSC04223



DSC04224



DSC04225



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956