Photo Album for Waterloo Fire Rescue, IA Job 35603 April 16, 2021

In this report your cab started assembly, the frame build continued, the pump house was merged with the pump, and the body continued fabrication. In your next report your cab and frame may continue assembly while the pump house may be painted, and the body releases to paint.



DSC04997



DSC04999



DSC04998



DSC05000





DSC05001



DSC04926



DSC04925



DSC04927





DSC04928



DSC00233



DSC04929



DSC00234






DSC00235



DSC00237



DSC00236



DSC00200





DSC00201



DSC00203



DSC00202



DSC00204





http://reliantfire.com/



An Oshkosh Corporation Company

