



Photo Album for Marshalltown Fire Department, IA Job 35684 May 14, 2021

In this report your cab began the paint process while your forward body module was fabricated. In your next report your cab may continue through paint while your forward body module may begin the paint process.



DSC02017



DSC02018




DSC02019



DSC02020



DSC02021



DSC00097



DSC00098



DSC00099



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

