




Photo Album for Marshalltown Fire Department, IA Job 35684 May 21, 2021

In this report your cab continued the paint process, your frame build began, and your forward body module was not available for photos. In your next report your cab may continue the paint process while your frame build continues, and your forward body module may be available for photos.



DSC02063



DSC02064




DSC02065



DSC02066



DSC02067



DSC00263



DSC00264



DSC00265



DSC00266



DSC00267



DSC00268



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

