Photo Album for Stanwood Fire Dept., IA Job # 35507 W/O # 26831113 May 22, 2021

This week the chassis was in staging (no photos), and the pump house structure was in staging (no photos). The fire pump was in staging (no photos), and the body continued with fabrication. Next week the chassis and pump house structure should be in staging and the fire pump should begin to receive valves and plumbing. The body should finish with fabrication.



DSC00045



DSC00047



DSC00046



DSC00048





http://reliantfire.com/



**An Oshkosh Corporation Company** 



