Photo Album for Marshalltown Fire Department, IA Job 35684 May 28, 2021

In this report your cab started assembly while the frame build continued, the water pump arrived, the forward body module was not available, and the body started fabrication. In your next report the cab and frame assembly may continue while the forward body module may be available, and the body continues fabrication.



DSC03088



DSC03090



DSC03089




DSC03091





DSC03092



DSC03073



DSC03072



DSC03074





DSC03075



DSC03746



DSC03076



DSC03747




DSC03748



DSC03750



DSC03749



DSC00015



DSC00016



DSC00018



DSC00017



DSC00019





http://reliantfire.com/



An Oshkosh Corporation Company



