



# Photo Album for Marshalltown Fire Department, IA Job 35684 June 04, 2021

In this report your cab and frame continued assembly while the front body completed paint and the body continued fabrication. In your next report the cab and frame assembly may continue while the forward body module may receive plumbing, and the body continues fabrication.



DSC03160



DSC03161



DSC03162



DSC03163



DSC03164



DSC03201



DSC03202




DSC03203



DSC03204



DSC03205



DSC03858



DSC03859



DSC03860



DSC03861



DSC03862



DSC00200



DSC00201



DSC00044



DSC00045



DSC00046



DSC00047



DSC00048



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956