Photo Album for Stanwood Fire Dept., IA Job # 35507 W/O # 26831113 May 29, 2021

This week the chassis was in staging (no photos), and the pump house structure was in staging. The fire pump was in staging, and the body finished with fabrication. Next week the chassis and pump house structure should be in staging and the fire pump should begin to receive valves and plumbing. The body may begin the paint process.



DSC00053



DSC00055



DSC00054



DSC00056





DSC00057



DSC00059

Find us on Facebook



DSC00058



DSC00060



DSC00109



DSC00111



DSC00110



DSC00112





http://reliantfire.com/



An Oshkosh Corporation Company



