



# Photo Album for Stanwood Fire Dept., IA

Job # 35507

W/O # 26831113

June 12, 2021

Since the last report, the chassis was in staging, and the pump house structure was in staging (no photos). The fire pump was in staging, and the body began the paint process. Next week the chassis and pump house structure should be in staging and the fire pump should begin to receive valves and plumbing. The body may finish with paint.





DSC00081



DSC00082



DSC00083



DSC00084





DSC00085



DSC00086



DSC00087



DSC00088





DSC00377



DSC00378



DSC00379



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

© 2005-2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956