


Photo Album for Harlan Fire Department IA Job 35928 July 16, 2021

In this report your cab continued the paint process while the frame build began, the pump house began assembly, and the body started fabrication. In your next report your cab may continue in paint, the frame build, and pump house assembly may continue while the body continues fabrication.



DSC04455



DSC04456



DSC04457



DSC04458



DSC04459



DSC02239



DSC02240




DSC02241



DSC02242



DSC02243



DSC00318



DSC00319




DSC00320



DSC00321



DSC00322



DSC00248



DSC00249



DSC00250



DSC00251



DSC00252



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956