




Photo Album for Harlan Fire Department IA Job 35928 July 23, 2021

In this report your cab and frame continued assembly while the pump house was painted, and the body continued fabrication. In your next report your cab and frame may continue assembly while the pump house completes assembly, and the body completes fabrication.



DSC04824



DSC04825



DSC04826



DSC04827



DSC04828



DSC01839



DSC01840



DSC01841



DSC01842



DSC01843



DSC00213



DSC00214




DSC00215



DSC00216



DSC00217



DSC00192



DSC00193



DSC00194



DSC00195



DSC00196



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956