


# Photo Album for Marshalltown Fire Department, IA Job 35683 July 16, 2021

In this report your cab was merged with the chassis while the body completed initial assembly. In your next report the body may be merged with the chassis followed by the start of final assembly.



DSC04752



DSC04753



DSC04754



DSC04755



DSC04756



DSC04757



DSC04758



DSC04759



DSC04760



DSC04761



DSC04762



DSC04763



DSC04764



DSC04765



DSC04766



DSC04767



DSC04768



DSC04769



DSC04770



DSC04771



DSC04772



DSC04773



DSC04774



DSC04775



DSC04776



DSC04777



DSC04778



DSC04779





DSC04780



DSC04781



DSC04782



DSC04783



DSC04784



DSC04785



DSC04786



DSC04787



DSC04788



DSC04789



DSC04790



DSC04791



DSC04792



DSC04793



DSC04794



DSC04795



DSC04796



DSC04797



DSC04798



DSC04799



DSC04800



DSC04801



DSC04802



DSC04803



DSC04804



DSC04805



DSC04806



DSC04807



DSC04808



DSC04809



DSC04810



DSC04811





DSC04812



DSC04813



DSC04814



DSC04815



DSC04816



DSC04563



DSC04564



DSC04565



DSC04566



DSC04567



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956