## Photo Album for Wauwatosa Fire Department, WI Job 35764-02 July 09, 2021

In this report your cab and pump house were merged with the chassis while the body completed paint followed by initial assembly. In your next report the body may be merged with the chassis followed by the start of final assembly.



DSC05193



DSC05195



DSC05194



DSC05196





DSC05197



DSC05199



DSC05198



DSC05200





DSC05201



DSC05203

Find us on Facebook



DSC05202




DSC05204



DSC05205



DSC05207



DSC05206



DSC05208





DSC05209



DSC05211



DSC05210



DSC05212



DSC05213



DSC05215



DSC05214



DSC05216





DSC05217



DSC05219



DSC05218




DSC05220





DSC05221



DSC05223



DSC05222



DSC05224





DSC05225



DSC05227



DSC05226



DSC05228





DSC05229



DSC05231



DSC05230



DSC05232





DSC05233



DSC05235



DSC05234



DSC05236





DSC05237



DSC05239



DSC05238



DSC05240





DSC05241



DSC05243



DSC05242



DSC05244



DSC05245



DSC05247



DSC05246



DSC05248





DSC05249



DSC05251

Find us on Facebook




DSC05250



DSC05252



DSC05253



DSC05255



DSC05254



DSC05256





DSC05257



DSC05259



DSC05258



DSC05260





DSC05261



DSC05263



DSC05262



DSC05264





DSC05265



DSC04575



DSC04574



DSC04576









DSC04578





http://reliantfire.com/



**An Oshkosh Corporation Company** 



