



Photo Album for City of Urbandale, IA Job 36002 August 20, 2021

In this report your cab and pump house were merged with the chassis while the body completed initial assembly. In your next report the body may be merged with the chassis.





DSC04928



DSC04929



DSC04930



DSC04931



DSC04932



DSC04933



DSC04934



DSC04935



DSC04936



DSC04937




DSC04938



DSC04939



DSC04940




DSC04941



DSC04942



DSC04943



DSC04944



DSC04945



DSC04946




DSC04947



DSC04948



DSC04949



DSC04950



DSC04951



DSC04952



DSC04953



DSC04954




DSC04955



DSC04956



DSC04957



DSC04958



DSC04770



DSC04771



DSC04772



DSC04773



DSC04774



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956