

Photo Album for Mineral Point Fire Department, WI Job 36161 November 05, 2021

In this report your cab is staged for assembly while the frame build continued, the pump house continued assembly, and the torque box remained staged. In your next report, your cab may begin assembly while the frame is staged, the pump house assembly may continue, and the torque box is staged.



DSC04405



DSC04406




DSC04407



DSC04408



DSC04409



DSC01303



DSC01304



DSC01305



DSC01306



DSC01307



DSC01308



DSC00087



DSC00088



DSC00089



DSC00090



DSC00091



DSC00130



DSC00131



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956