

Photo Album for Mineral Point Fire Department, WI Job 36161 November 12, 2021

In this report your cab started assembly while the frame is staged, the pump house continued assembly, and the torque box remained staged. In your next report, your cab may continue assembly while the frame is staged, the pump house may be staged, and the torque box is staged.



DSC05169



DSC05170




DSC05171



DSC05172



DSC05173



DSC01242



DSC01243



DSC01244



DSC01245



DSC01246



DSC01247



DSC00082



DSC00083



DSC00084



DSC00139



DSC00140



DSC05077



DSC05078



DSC05079



DSC05080



DSC05081



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956