

Photo Album for Mineral Point Fire Department, WI Job 36161 December 03, 2021

In this report your torque box is being installed on the chassis, the body completed initial assembly, and the aerial device sections arrived. In your next report, torque box installation may be completed while the body and aerial device sections are staged.



DSC00220




DSC00221



DSC00222



DSC00223



DSC00224



DSC00225



DSC00226



DSC00227



DSC00228



DSC00229



DSC00230



DSC00231



DSC00232



DSC00233



DSC00234



DSC04805



DSC04806




DSC04807



DSC04808



DSC04809



DSC00193



DSC00194



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956