

Photo Album for Mineral Point Fire Department, WI Job 36161 December 10, 2021

In this report the body was installed followed by the start of final assembly while the aerial device started assembly. In your next report final assembly of the apparatus may continue and the aerial device may continue assembly.




DSC01363



DSC01364



DSC01365




DSC01366



DSC01367



DSC01368



DSC01369




DSC01370



DSC01371



DSC01372



DSC01373



DSC01374



DSC01375



DSC01376



DSC01377



DSC01378



DSC01379



DSC01380



DSC01381



DSC01382



DSC01383



DSC01384



DSC01385



DSC01386



DSC01387



DSC01388



DSC01389



DSC01390




DSC01391



DSC01392



DSC01393



DSC01394



DSC01395



DSC01396



DSC01397



DSC01398



DSC01399



DSC01400



DSC01401




DSC01402



DSC01403



DSC01404




DSC01405



DSC01406



DSC01407



DSC00155



DSC00156



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956