

Photo Album for West Des Moines Fire Department, IA Job 36203 December 10, 2021

In this report your tractor cab began in paint while your tiller cab was fabricated and began the paint process. In your next report your cabs may continue the paint process.



DSC04537



DSC04538




DSC04539



DSC04540



DSC04541



DSC04542



DSC04543



DSC04544



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

