



Photo Album for Ames, IA Job 36258 January 14, 2022

In this report your cab is staged, the frame build continued, the pump house completed paint, and the body is staged for initial assembly. In your next report the cab may be staged while the frame build continues, the pump house may begin assembly, and the body is staged.



DSC04642



DSC04643




DSC04644



DSC04645



DSC04646



DSC01346



DSC01347




DSC01348



DSC01349



DSC01350



DSC00061



DSC00062




DSC00063



DSC00064




DSC00065



DSC00165



DSC00166



DSC01154



DSC01155




DSC01156



DSC01157



DSC01158



DSC00113



DSC00114



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

