




Photo Album for West Des Moines Fire Department, IA Job 36203 January 14, 2022

In this report your tractor cab completed assembly, the pump house is being painted, the body modules started fabrication, the trailer and tiller cab are staged, and the aerial device sections have arrived. In your next report the tractor cab may be staged, the pump house may continue in paint, body module fabrication may continue, and the trailer, tiller cab, and aerial device may be staged.



DSC04617



DSC04618



DSC04619



DSC04620



DSC04621




DSC04557



DSC04558




DSC04559



DSC00032



DSC00033



DSC00044



DSC00045



DSC00046



DSC00047



DSC00048



DSC00049



DSC00050



DSC00051



DSC00052



DSC01134



DSC01135




DSC01136



DSC01137



DSC01138



DSC00066



DSC00067



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

