
Photo Album for West Des Moines Fire Department, IA Job 36203 January 21, 2022

In this report your tractor cab is staged, the pump house started the assembly process, two of the three body modules completed fabrication with one not available, the tiller cab is staged, the aerial device sections are staged, and the trailer is not available for photos. In your next report the tractor cab may remain staged, the pump house may continue assembly, the two body modules may continue in paint, the third module may be available again along with the trailer for photos while the tiller cab, and aerial device may be staged.



DSC04655



DSC04657



DSC04656



DSC04658





DSC04659



DSC00094



DSC00093



DSC00095





DSC00096



DSC04504

Find us on Facebook



DSC00097



DSC04505




DSC04506



DSC04508



DSC04507



DSC04514





DSC04515



DSC04517



DSC04516



DSC04518





DSC01096



DSC01098



DSC01097



DSC01099





DSC01100



DSC00087



DSC00086





http://reliantfire.com/



An Oshkosh Corporation Company



