

# Photo Album for West Des Moines Fire Department, IA Job 36203

## February 11, 2022

In this report your tractor cab and pump house were merged with the frame, the front two body modules started initial assembly, the rear body module is staged, the tiller cab is staged, and the trailer started assembly. In addition, the aerial device is staged with no photos. In your next report the tractor chassis may complete assembly, the trailer assembly may continue, the body modules may continue initial assembly, and the aerial device and tiller cab may remain staged.



DSC01333




DSC01334



DSC01335



DSC01336



DSC01337



DSC01338



DSC01339



DSC01340



DSC01341



DSC01342



DSC01343



DSC01344



DSC01345



DSC01346



DSC01347



DSC01348



DSC01349



DSC01350



DSC01351



DSC01352



DSC01353



DSC01354



DSC01355




DSC01356



DSC01357



DSC01358



DSC01359



DSC01360



DSC01361



DSC01362



DSC01363



DSC01364



DSC01365



DSC01366



DSC01367



DSC01368



DSC01369



DSC01370



DSC01371



DSC01372



DSC01373



DSC01374



DSC01375



DSC01376



DSC01377



DSC01378



DSC01379



DSC01380



DSC01381



DSC01382



DSC01383



DSC01384



DSC01385



DSC01386



DSC01387



DSC01388



DSC01389



DSC01390



DSC01391



DSC01392



DSC01393



DSC01394



DSC01395




DSC01396



DSC01397



DSC01398



DSC01399



DSC01400



DSC01401



DSC01402



DSC01403



DSC01404



DSC01405



DSC01406




DSC01407



DSC01408



DSC05377



DSC05378



DSC05379



DSC01016



DSC01017



DSC01018



DSC01019



DSC01020



DSC01021



DSC01022



DSC01023



DSC01024



DSC01025



DSC01026



DSC01027



DSC01028



DSC01029



DSC01030



DSC01031



DSC01032



DSC01033



DSC01034



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

