
Photo Album for West Des Moines Fire Department, IA Job 36203 February 18, 2022

In this report your chassis continued assembly, the three body modules continued initial assembly, the trailer continued assembly, and the tiller cab started assembly. In addition, the aerial device is staged with no photos. In your next report the tractor chassis may be staged, the trailer assembly may continue, the body modules and tiller cab may continue assembly, and the aerial device may remain staged.



DSC01032



DSC01034

Find us on Facebook



DSC01033




DSC01035



DSC01036



DSC01038



DSC01037




DSC01039





DSC01040



DSC01042



DSC01041



DSC01043





DSC01044




DSC01046



DSC01045




DSC01047



DSC01048



DSC01050



DSC01049




DSC01051





DSC01052



DSC01021



DSC01020



DSC01022






DSC01023



DSC01025



DSC01024



DSC01026





DSC01027



DSC01029



DSC01028



DSC01030






DSC01031



DSC01016




DSC01015



DSC01017









DSC01019





http://reliantfire.com/



An Oshkosh Corporation Company



