


Photo Album for McFarland Fire and Rescue, WI Job 36382 March 25, 2022

In this report your cab started initial assembly, the frame build started, the front body started in paint, the rear body completed fabrication, the torque box arrived, and the aerial device sections remain staged with no photos. In your next report the cab may continue assembly, the frame build may continue, the body modules may make progress in paint while the torque box and aerial device are staged with no photos until assembly begins.



DSC04965




DSC04966



DSC04967



DSC04968



DSC04969



DSC00213



DSC00214



DSC00215



DSC00216



DSC00217



DSC00218



DSC05216



DSC05217



DSC05218



DSC04702



DSC04703



DSC04704



DSC04818



DSC04819



DSC04820



DSC04821



DSC04822



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety



©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956