
## Photo Album for McFarland Fire and Rescue, WI Job 36382 April 01, 2022

In this report your cab continued initial assembly, the frame build continued, the front body continued in paint (not available for photos), the rear body started in paint, and the torque box and the aerial device sections remain staged with no photos. In your next report the cab may continue assembly, the frame build may continue, the body modules may make progress in paint while the torque box and aerial device are staged with no photos until assembly begins.



DSC04847



DSC04849



DSC04848



DSC04850





DSC04851



DSC00263



DSC00262



DSC00264





DSC00265



DSC00267




DSC00266



DSC00268





DSC04484



DSC04486



DSC04485



DSC04487



DSC04488





http://reliantfire.com/



An Oshkosh Corporation Company



