



# Photo Album for City of Iowa City Fire Department, IA Job 36560 June 24, 2022

In this report your cab started initial assembly, the frame build continued, the pump house structure was painted, and the body completed paint . In the next report the cab may continue initial assembly, the frame build may continue, the pump house may start to be built, and the body may remain staged for initial assembly.



DSC04365



DSC04366



DSC04367



DSC04368



DSC04369



DSC04406



DSC04407



DSC04408



DSC04409



DSC04410



DSC07076



DSC07077



DSC01091



DSC01092



DSC01093



DSC04229



DSC04230



DSC04231



DSC04232



DSC04233



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2022 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956