

Photo Album for Sauk City Fire Department, WI Job 36820 June 24, 2022

In this report your cab started initial assembly while the frame build continued, the front body module was painted, and the rear body was fabricated with release to paint. In the next report your cab may continue initial assembly, the frame build may continue, the front body module may be staged, and the rear body may begin the paint process.





DSC04346





DSC04348 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC01116






© 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01120





DSC00125 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956





DSC04246 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956





DSC00126













http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

