Photo Album for Lake Mills Fire Department, WI Job 37717 August 26, 2022

In this report your cab started initial assembly, the frame build continued, the pump house began assembly, and the body began the paint process. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue assembly, and the body may continue through paint.



DSC01197



DSC01199



DSC01198



DSC01200





DSC01201



DSC04599



DSC04598



DSC04600





DSC04601



DSC04603



DSC04602



DSC04604





DSC04605



DSC07074



DSC07073



DSC07075





DSC07076



DSC07237



DSC07077



DSC07238





DSC07239



DSC07241



DSC07240





http://reliantfire.com/



An Oshkosh Corporation Company



