## Photo Album for Pella Fire Department, IA Job 36829 August 26, 2022


In this report your cab began initial assembly, the frame build continued, and your body began the paint process. In the next report your cab may continue initial assembly, the frame build may continue, and your body may continue through paint.





DSC04826





DSC04828 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01145





DSC01147 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







				6.10	
No. No. 1					
	MFG B	Y: TANKC	RAFT		
	DARIEN, WI				
	MEETS ALL F.M.C.S REQUIREMENTS	A. NON SIDE PART NO.	MOUNTED TANK 1346933		
	DATE: 03/2022	LIQUID CAP	PACITY		
	MO/YEAR	(U.S. GALL	ONS):65		
	WARNING: DO NOT FILL T 95% OF LIQUI		DIESEL FUEL ONLY		
	المراقع ورا				

DSC01149





DSC01151 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



f





DSC04704





DSC04706 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

