
Photo Album for Lake Mills Fire Department, WI Job 37717 September 02, 2022

In this report your cab completed initial assembly while the pump house completed assembly, and both were merged with the frame. The body completed paint and began initial assembly. In the next report your chassis assembly may continue while the body may continue initial assembly.



DSC07280



DSC07282



DSC07281



DSC07283



DSC07284



DSC01180



DSC01179



DSC01181









DSC01183





http://reliantfire.com/



An Oshkosh Corporation Company



