




# Photo Album for Pella Fire Department, IA Job 36829 September 09, 2022

In this report your cab was merged with the frame, the pump house completed initial assembly and was staged, and your body continued through paint. In the next report your chassis may continue assembly, the pump house may remain staged, and your body may continue the paint process.



DSC01316



DSC01317



DSC01318



DSC01319





DSC01320



DSC01321



DSC01322



DSC01323





DSC01324



DSC01325



DSC01326



DSC01327





DSC07222



DSC07223




DSC07224



DSC07225



DSC07226



DSC04628



DSC04629



DSC04630





DSC04631



DSC04632



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

