



Photo Album for Council Bluffs, IA Job 38453 October 07, 2022

In this report your cab continued the paint process, your pump house structure began fabrication, and your body remained staged. In the next report your cab may continue the paint process, your pump house structure may continue fabrication, and your body may begin the paint process.



DSC04989



DSC04990




DSC04991



DSC04992



DSC04993




DSC07060



DSC07061



DSC07062



DSC04740



DSC04741



DSC04742



DSC04743



DSC04744



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

