



Photo Album for Fort Dodge Fire Department, IA Job 37218 October 28, 2022

In this report your cab began initial assembly, the frame build began, your pump house started initial assembly, and your body completed fabrication and released to paint. In the next report your cab may continue initial assembly, the frame build may continue, your pump house may continue initial assembly, and your body may continue the paint process.



DSC05095



DSC05096




DSC05097



DSC05098



DSC05099



DSC01005



DSC01006




DSC01007



DSC01008



DSC01009



DSC07244



DSC07245




DSC07246



DSC07247



DSC07248



DSC04648



DSC04649



DSC04650



DSC04651



DSC04652



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956