




Photo Album for Norwalk Fire Department, IA Job 37124 October 28, 2022

In this report your cab began initial assembly, the frame build continued, and your body completed fabrication and released to paint. In the next report your cab may continue initial assembly, the frame build may continue, and your body may continue the paint process.



DSC05100



DSC05101



DSC05102



DSC05103



DSC05104



DSC04822



DSC04823



DSC04824



DSC04825



DSC04826




DSC04827



DSC04828



DSC04829



DSC04849



DSC04850



DSC04851



DSC04852



DSC04853



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

