



Photo Album for Fort Dodge Fire Department, IA Job 37218 November 04, 2022

In this report your cab was merged with the frame, your pump house continued initial assembly, and your body was staged to continue the paint process. In the next report your chassis may continue assembly, your pump house may continue initial assembly, and your body may continue through paint.



DSC01414



DSC01415



DSC01416



DSC01417



DSC01418



DSC01419



DSC01420



DSC01421



DSC01422



DSC01423



DSC01424



DSC01425



DSC01426



DSC01427



DSC01428



DSC01429



DSC01430



DSC01431



DSC01432



DSC01433



DSC01434



DSC01435



DSC01436



DSC01437



DSC01438



DSC01439



DSC01440



DSC01441



DSC01442



DSC01443




DSC01444



DSC01445



DSC01446



DSC01447



DSC01448



DSC01449



DSC01450



DSC01451



DSC01452



DSC01453



DSC01454



DSC01455



DSC01456



DSC01457



DSC01458



DSC01459



DSC01460



DSC01461



DSC01462



DSC01463



DSC01464



DSC01465



DSC01466



DSC01467



DSC01468



DSC01469



DSC01470



DSC01471




DSC01472



DSC01473



DSC01474



DSC07064



DSC07065




DSC07066



DSC07067



DSC07068



DSC04817



DSC04818



DSC04819



DSC04820



DSC04821



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

