Photo Album for Marion Fire Department, IA Job 37320 January 06, 2023

In this report your cab made progress through paint and was staged, the frame build began, your pump house was painted, and your body completed fabrication and was staged. In the next report your cab may remain staged to begin initial assembly, the frame build may continue, your pump house may continue initial assembly, and the body may begin the paint process.



DSC04820



DSC04822

Find us on Facebook



DSC04821



DSC04823



DSC04824



DSC01016



DSC01015



DSC01017






DSC01018



DSC07148



DSC01019




DSC07149





DSC07150



DSC07152



DSC07151



DSC04645





DSC04646



DSC04648



DSC04647



DSC04649





http://reliantfire.com/



An Oshkosh Corporation Company



